Note:- This roof & truss changed to timber construction of similar design see special details...

Revised Ridge line

Copper flash.

Nature Roof

This stencilled diaper to continue across end walls following line of curved members of truss

Stencil Gallery

Cream Stone finish

Plaster

Wood frame Lead Glazing Leaded in.

These busts are not included in Contract

An East wall only this portion of dados and also that in corresponding panel in N.E. corner to be a Tyndall Stone Base. To match.

Cream Stone finish

Glazed Wood Casement

Granite Coping

12" Marble Cap.

Granite coping

TEMPORARY SEMINAR ROOM.

STORE ROOM.

Vault door

WOMEN'S LOCKER ROOM.

4" Reinforced concrete

2" Split tile.

Collect Metal Casement

4" Tile

FAN CHAMBER & ENGINE ROOM.

Metal doors & Trim

Reversible Lantern

Angle Iron

PIPE DUCT

HALF LONGITUDINAL SECTION

CENTRE PORTION OF EASTERLY WALL OF CONCOURSE, SEE SHEET #5 for REMAINDER of ELEVATION.

CHIMNEY CAP.

EDGE VIEW

ROOF SIDE

Plastered two sides

Copper Flash.

Copper roof flash

Loose Conc Circle & Slabs

Cl. 451-6

Cotton wood boards

Cotton wood

Slate roof

Cotton wood. panels

Copper.

Cotton wood.

Cl. 426-9

Cl. 426-0

Ceiling furred down.

Brick relieving Arch

Metal Sash

Ash clumps

8'-6" Reding

Loose R.C. Lintol.

Plaster

Granite

Concrete curb.

OMIT this Mantle and set-over Supplied by the Government of B.C.

REVISED SECTION OF CONCOURSE ROOF SHEWING TIMBER CONSTRUCTION...

TEMPORARY BROWSING ROOM FIREPLACE

showing Flues and Ash clumps.

Revised Wood Roof

Built into concrete, hangers for purlins.

Revised height of Roof

Copper flashing

Tar & sand on asphaltic Roofing

R.C. Concrete Roof Trusses

Note:- In all cases such as this brickwork to be carried over as slab with thick Bituman coarse under.

Brick Wall

Wood Steel

Floor El. 335'

Tile to be carried over heads in South Wing

STAFF WORKROOM.

Plate Rail

This trim in Staff Workroom and Seminar Rooms

This trim in Secretary's & Librarian's Rooms also Browsing Rm which will have in addition Moulded dado rail

MEN'S LOCKER ROOM.

Quilt Wall Think Substitute Pulled Coons Cement

4" Split Tile

Floor Grading

Fin. Ground line.

Flr. El. 380'

Flr. El. 360'

Steel Floor Beam

SIDE WALL TREATMENT IN WING ROOMS.

HALF SECTION thro' WINGS.

Corrected to date. Dec 17

Scale 1/4" : 1 foot

September 29 1923

UNIVERSITY of B.C. The LIBRARY BLDG

Sharp & Thompson Architects